



Grid Connection

Connection Type 1 - Cell Wall to Cell Wall



Connection Type 2 - Weld End to Weld End



Staple Connection

Pneumatic Stapler




OR




Hand Held Stapler

Type 1 - Cell Wall Connection




- Use heavy
duty staples

Type 2 - Weld End Connection



Contact Information

Carthage Mills



4243 Hunt Road
Cincinnati, OH 45242
www.carthagemills.com

513-794-1600 TELEPHONE
800-543-4430 TOLL FREE
513-794-3434 FACSIMILE

Since 1958: America's *First* Geotextile Company